## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent

Patent No.: 7,590,251 Conf. No.: 9255
Inventor: Jack B. Andersen et al. Art Unit: 2614

Issue Date: September 15, 2009 Examiner: Suthers, Douglas John Appln, No.: 10/805,588 Atty, Docket No.: ELAN-01192US1

Filed: March 19, 2004

Title: CLIP DETECTION IN PWM AMPLIFIER | Customer No.: 23910

## REQUEST FOR CERTIFICATE OF CORRECTION UNDER 37 CFR §1.322

Certificate of Correction Branch Commissioner for Patents P.O. Box 1450

Alexandria, VA 22313-1450

Sir:

It is hereby certified that a certain error appears in the above-identified U.S. patent. The requested correction is being made to correct an error in the claims of the patent and is presented on the attached PTO/SB/44 form.

Pursuant to 37 C.F.R. § 1.322(a)(1)(i), the undersigned attorney of record, as a representative of the patentee or the patentee's assignee, requests that a Certificate of Correction be issued.

No fee is believed due in connection with this paper. However, the Commissioner is authorized to charge any underpayment or credit any overpayment to Deposit Account No. 06-1326 for any matter in connection with this paper, which may be required.

Respectfully submitted.

Date: October 5, 2009 By: /Jeffrey R, Kurin/
Jeffrey R, Kurin

Reg. No. 41,132

FLIESLER MEYER LLP 650 California Street, 14<sup>th</sup> Floor San Francisco, California 94108 Telephone: (415) 362-3800 Facsimile: (415) 362-2928